

HIGHLIGHT EXPERT KITS+ V10-6991-XXL OIL PUMP VW DSG® (DQ381)

TRANSMISSION OIL PUMPS | 22202

Information

The new 7-speed DSG® (DQ381) from VW has a weakness: Oil loss can occur in the area of the oil pump. Malfunctions of the pump cause various error codes to be stored in the memory, while the transmission then often switches to emergency mode. These faults can be easily remedied by replacing the oil pump and then clearing the fault memory. In addition, the pump change should generally be combined with an oil change on the transmission. Here, VAICO also has the right EXPERT KIT + for you: **V10-6991-XXL**.



SYMPTOMS

- Transmission switches to emergency mode
- Oil loss at the transmission
- Error codes: P0C29, P175E, P176E, P1899



REASONS FOR FAILURE

- Faulty electrohydraulic oil pump V475



SOLUTION

- Replacing the transmission oil pump



ADVANTAGES

- **EXCLUSIVE!** Only available from VAICO
- Pump & filter in OE quality
- Oil – **MADE IN GERMANY**
- All required assembly parts & oil included in the EXPERT KIT+.
- Installation video:
<https://youtu.be/DvbOuILCJ0o>



Visit also our new online shop!
www.vierol-shop.de/en