

If the wrong version of the oil pump is installed, it could cause issues with the supply of oil to the engine due to the relevant Oil Galleries being in the wrong location for the engine block.



The main differences between both the oil pumps in terms of design is position and design of the oil galleries.

Applications OP351	OE REFERENCE	Applications OP382	OE REFERENCE
Mercedes-Benz	A6511800400	Mercedes-Benz	A6511801500
	A6511801301		
	A6511802001		
	A6511802401		
	A6511802601		
	A651182801		
Jeep	K68089287AA K68089288AA K68089288AB		