

Important technical note relating to this unit

Possible issues relating to charging problems:

1. One Amp fuse is sometimes defective, this can be found in the main fuse box in the engine bay
2. The wiring harness from factory is too tight resulting in broken wires in the harness, the wires are mostly broken under headlight
3. Corrosion inside the multi connector on the rear of the unit is also common.