



# febi 44945

**to fit:**

Audi, Seat, Skoda, Volkswagen,  
Mitsubishi, various models  
1.9 & 2.0 TDi Engines



## Throttle Body

### Problem

Engine management lamp illuminated, poor performance, increased engine temperature and/or engine shuddering during switch off. Fault codes logged relating to the throttle body, intake manifold flap and coolant fan motor.

### Cause

The above symptoms can be caused by an excessive build-up of carbon deposits, failed throttle body drive components or a seized throttle plate. This results in a blown fuse which protects both the cooling fan and throttle body circuits.

### Solution

Check and rectify all circuits relating to the faulty component and replace throttle body.

For more technical information please visit: [partsfinder.bilsteingroup.com](https://partsfinder.bilsteingroup.com)