

febi 1001193, 1001194



To fit: Various Volkswagen, Audi, SEAT
and Škoda models



Anti Roll Bar Bush

Problem

Squeaking and creaking noises from the front suspension when traveling on uneven surfaces.

Cause

With age and increased mileage, the anti-roll bar rubber bushes deteriorate and no longer provide the same level of support as when the vehicle was new.

Solution

On many Volkswagen Group vehicles built on the MQB platform, the manufacturer does not supply these anti-roll bar bushes separately. febi offers them as individual components, allowing for a more efficient repair without the need to replace the entire anti-roll bar.

For more technical information please visit: partsfinder.bilsteingroup.com