



INA Service Info



Belt tensioner 534 0075 20

Visual differences

Manufacturers: Citroën, Ford, Mazda, Mini, Peugeot, Suzuki, Toyota, Volvo

Models:

Citroën: Berlingo, C-Elysse, C1, C2, C3 I, C3 II, C4 I, C4 II, C5 III, DS3, DS4, DS5

Ford: B-Max, C-Max, C-Max II, Grand C-Max, Fiesta V, Fiesta VI, Focus C-Max, Focus II, Focus III, Fusion, Galaxy, Mondeo IV, S-Max 2, 3

Mazda:

Mini: Cooper, One

Peugeot: 107, 206, 207, 208, 301, 307, 308, 308 II, 408, 508, 1007, 2008, 3008, 4008, 5008, Partner

Suzuki:

Toyota: Aygo

Volvo: C30, S40 II, S80 II, V50, V70 III

Engines:

Citroën/Peugeot: 1.4 HDI, 1.6 HDI

Ford: 1.4 TDCI, 1.5 TDCI, 1.6 TDCI

Mazda: 1.4 MZR-CD, 1.6 DI Turbo, 1.6 MZ-CD, 1.6 MZR-CD

Mini/Volvo: 1.6 D

Suzuki: 1.6 DDIS

Toyota: 1.4 HDI

Part no.: 529 0036 10
529 0061 10
529 0062 10
529 0065 10
529 0066 10
534 0075 20




Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the belt tensioner with part number 534 0075 20.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk