

## THIS STRUT IS FILLED WITH A MAGNETIC FLUID COMPOUND



Struts stored in one position (static) for an extended period can cause the magnetic fluid to separate into its constituent materials.

This can cause the damper to seem as if it is stiff or seized.

THIS IS TO BE EXPECTED AND COMPLETELY NORMAL.
THE SHOCK WILL FUNCTION AS INTENDED ONCE IN USE.



## **Arnott US Business Office:**

www.arnottinc.com

100 Sea Ray Drive Merritt Island, FL 32953

**Call:** 800.251.8993

321.868.3016

**Fax:** 321.868.3703

**Email:** techassistance@arnottinc.com

## **Arnott Europe Business Office:**

www.arnotteurope.com

Docterskampstraat 1E/1F, 3 5222 AM 's-Hertogenbosch (NL)

NL Phone: +31 73 7850 580

DE Phone: +31 85 2087 438

UK Phone: +44 203 3186 124

BE Phone: +32 258 846 90

ES Phone: +34 91 901 10 56

**FR Phone:** +32 78 48 46 93

**Email:** info@arnotteurope.com



Air Springs



Struts



Shocks



Compressors



Dryers



Coil Spring Conversion Kits



Valve Blocks



Ride Height Sensors