

Blue Print ADP153316

To Fit:

Various Peugeot and Citroen models



EN

Clutch Release Fork

Problem

Difficulty in selecting gears when the clutch pedal is depressed, and a grating noise can also be heard when the clutch pedal is operated, this can be felt through the clutch pedal.

Cause

As the clutch wears and dust and debris build up, resistance in the clutch release mechanism increases putting more strain on the release fork. This causes the plastic bearing cup, which the release fork pivots on, to wear or break.

Solution

On removal of the transmission, inspect the clutch release fork, guide tube and clutch assembly and replace any worn or broken parts as necessary.

For more technical information please visit: partsfinder.bilsteingroup.com