Certified Automotive Parts Association
Washington, DC

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM
CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	32398
Notification Date / 通知日期:	01/17/2018
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709

Participant Part Number / 零件號碼:	AD-10039AQ-LH
Car Company Service (CCS) Part Number 原廠零件編號:	8W0821105A
Partslink Number / 號碼:	AU1240137
Part Description / 零件種類:	Fender L
Application Description / 車種年份:	Audi A4, 17-18

Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply.

備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊.

Applicable CAPA Certification Standard / 適用之CAPA認證標準: 101 Metals

Status Affects / 受影響狀態: [X] Part Number / 零件編號 [X] Lot Number / 批號: 01/18A

Status as of this Notice / **通知後狀態:** **NEW PART APPROVAL**



Reason for Status Change: **狀態變更原因:**

- [ ] Participant Request / 廠商要求
- [ ] Production Inspection 產品檢驗
- [ ] CAR / 改善措施要求
- [ ] Random Material Testing 隨機抽樣材測
- [ ] MM VTF / 市場觀察合車
- [X] Other - Describe: 其他 - 請詳述: NPA – passed dimension test.

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註 ：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

CAPA Validator Use Only / 僅供CAPA 驗證機構使用

Submitted By / 提案人:	Issued By / 簽發者:
CAPA Validator Signature: CAPA 驗證機構簽名: 	CAPA Administrator Signature: CAPA 行政人員簽名: 

© 2018 CAPA