TRUNK LATCH ACTUATOR RELAY LEVER UPGRADE KIT

for AUDI and VW

OE: 1J5 827 567A

Triscan SELECT: 8900 29588

OEM Design

The trunk release actuator found in the VW Jetta MK4 is known for breaking the thin plastic relay lever, which disables the latch release mechanism. Repair typically requires replacement of the entire actuator bracket assembly, which is no more durable than the original failure-prone assembly.



Problems

- Actuator usage breaks the plastic relay lever, especially during cold weather.
- Replacement of OE bracket assembly is a costly yet temporary repair, and doesn't resolve the fragile relay lever issue.

TRISCAN SELECT

Triscan SELECT redesigned the plastic actuator relay lever using metal for vastly improved reliability. The Triscan SELECT lever is made of sturdy aluminium and reinforced with structural ribs, making the lever exponentially stronger than OE. Now you can permanently repair the actuator bracket instead of replacing it!



Advantages

- Improved design corrects OE deficiencies.
- Triscan SELECT relay lever is simple to install.
- Aluminium construction is impervious to summer heat and winter cold.
- Lifetime warranty.

Vehicle Applications

1999-2005 Volkswagen Bora and Jetta MK4