Certified Automotive Parts Association
Washington, DC


NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	17381
Notification Date / 通知日期:	03/30/2012
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	[X] CAPA 101 [ ] CAPA 201 [ ] CAPA 301 [ ] CAPA 501 [ ] CAPA 201A [ ] CAPA 401
Participant Part Number / 零件號碼:	FD-20147AQ
Car Company Part Number / CCS 號碼:	7T1Z16612A — Partslink Number / 號碼: FO1230288
Part Description / 零件種類:	Hood
Application Description / 車種年份:	Ford Transit Connect, 10-12
Status Affects / 受影響狀態:	[X] Part Number / 零件編號 [X] Lot Number / 批號: 01/12A
Status as of this Notice / 通知後狀態:	**NEW PART APPROVAL**
Reason for Status Change / 狀態變更原因:	[ ] Participant Request / 廠商要求 [ ] Production Inspection 產品檢驗 [ ] CAR / 改善措施要求
	[ ] Random Material Testing 隨機抽樣材測 [ ] MM VTF / 市場觀察合車 [X] Other / 其他:
Describe / 原因:	NPA – passed dimension test.
Seal Size: / 標籤尺寸:	[X] Standard / 標準 [ ] Alternative / 替代選擇

NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.

註 ：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表爲零件重新註冊, 並繳交新零件核可費用。

Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator

© 2012 CAPA