The spare parts experts of
Volkswagen BMW Mercedes-Benz



STO

Superior To OE

STO Fuel Tank Breather Valve

The spare parts experts of
Volkswagen BMW Mercedes-Benz

STO Fuel Tank Breather Valve

Produced by OE supporting factory

4 Years

STO


Common issue

Unstable idle speed, engine check light on.


Applicable models

B38;B48;B46;B48;B58;S58

Valve Core



vika




OE

vika: Linear speed pins of the valve core are resistance welded, which is less likely to fall off and more secure.

OE: The valve core is soldered, which can easily cause the copper wire to be scratched.

Valve Sleeve



vika




OE


vika: The adjustable valve body ensures sealing precision and is more durable.

OE: Non-adjustable valve body, poor sealing performance.

Moving Iron Core



vika



OE

vika: The armature sub-assembly sheet structure is used for sealing, which has a better sealing effect.

OE: The leather cup structure has poor sealing performance during long-term moving.