



THE SYMPTOMS

- Engine damage.
- Valve breakage.
- Poor performance.

THE REASON

- Wrong Valve is being installed.

VALVE APPLICATION

1.8 L, 20 Valve, 4 Cylinder Engines


2.8 L, 30 Valve, 6 Cylinder Engines

THE SOLUTION

- Always double check the VIN code before ordering.
- Check that the correct Valve is to be installed.

CLICK ON THE VALVE BELOW FOR FULL APPLICATION INFORMATION

V033394




<http://catalogue.bgautomotive.co.uk/search?type=App&id=V033394>

V033413



<http://catalogue.bgautomotive.co.uk/search?type=App&id=V033413>

V033438



<http://catalogue.bgautomotive.co.uk/search?type=App&id=V033438>

BGA PART NUMBER	VALVE TYPE	OE NUMBER	HEAD DIAMETER	STEM DIAMETER	LENGTH
V033394	Exhaust Valve	058 109 611E	29.8mm	6mm	103.9mm
V033413	Inlet Valve	058 109 601C	26.9mm	6mm	105.1mm
V033438	Exhaust Valve	058 109 611M	29.8mm	6mm	103.9mm



BGA products are to be replaced by an experienced automotive installer. This information is to be used as reference only. Always seek manufacturer specification.

