

Repair solution for the exhaust manifold gasket

940.480 | Citroën | Peugeot | DS | Fiat | Opel | Toyota | Ford | Vauxhall

Elring offers a repair solution for the exhaust manifold without requiring the complete replacement of the heat protection shield. As only the exhaust manifold gasket needs to be replaced, our repair solution re-uses the existing heat protection shield. Our new gasket installs without the use of rivets.



Citroën | Peugeot | DS

98 162 672 80

Opel

35 53 746

Toyota

SU001-A8003

Ford


2 190 817 | JX6Q 9448 AA




1.




2.




3.



4.



5.



ElringKlinger AG | Aftermarket Division

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

SI 04/2024



Das Original