



Service Info



Change affecting hydraulic bucket tappet

Manufacturers: Alfa Romeo, Fiat, Lancia, Rover

Models:

Alfa Romeo: 145, 146, 147, 155, 156, 166, GT, GTV, Spider

Fiat: Barchetta, Brava, Bravo I, Coupe, Doblo, Marea, Multipla, Palio, Punto, Siena, Stilo

Lancia: Kappa, Lybra, Thesis

Rover: 100, 200, 400, 600, 800, Carbrio

Engines: 1.6, 1.6 16V, 1.7 T.S. 16V, 1.8 16V, 2.0, 2.0 16V, 2.0 20V, 2.4 20V

Part no.: 420 0050 10
420 0208 10

OE number:

Fiat: 464103078
73503122



Figure 1: Hydraulic bucket tappet: left: old version, right: new version

The vehicle manufacturers for the models specified above have changed the installation height of the hydraulic bucket tappet. Accordingly, Schaeffler Automotive Aftermarket is offering a modified version in the aftermarket.

The new hydraulic bucket tappet is 2 mm higher. Although the installation height is now different, the new bucket tappet can be fitted in the specified engines without any problems. The two versions do not differ in terms of their technical function.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.



Figure 2: Hydraulic bucket tappet, left: old version, right: new version

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-info@schaeffler.com
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

