



Product Awareness

**EXCLUSIVE
TO FAI**

LR350

Camshaft Carrier for BMW / MINI 2.0D / 1.6D N47 Variants

A common occurrence in the BMW N47 engine variants is Timing Chain Kit failure. When this occurs, the Camshaft Carrier has a tendency to fracture in one corner making it a popular replacement component. Our LR350 includes all cam caps, cam cap bolts and O-Rings.



Manufacturer	Model Details	Engine	Dates	Eng. Code	OE Ref.
BMW	1, 2, 3, 4, 5	2.0 D 1.6 D	2005 >	N47 D20 A	11317797511
	X1, X3, X5			N47 D20 B	
MINI	CLUBMAN	2.0 D 1.6 D	2005 >	N47 D20 C	
	COOPER COUNTRYMAN PACEMAN ROADSTER			N47 D20 D N47 C20 A N47 C16 A	

* See catalogue for full application info



**Best Availability. Best Value.
Best Quality. Best Service.**



+44 (0) 1525 351800



faiauto.com