

NEW PRODUCT HIGHLIGHT | OCT2020

SWAG[®]

SWAG 33 10 0269

33 10 0470, 33 10 0507, 33 10 0583

33 10 0593, 33 10 0667, 33 10 0668

To Fit:

Various Volkswagen, Audi,
Seat and Škoda models

Engine: 1.8 and 2.0 FSi, TFSi



EN

Oil Separator and Breather Hoses

Function

The pressure control and check valves, installed in the oil separator housing, regulates the suction as it separates the oil from the contaminated gases, according to engine speed, load and pressure ratio.

Failure

Over time, contamination causes reduced air flow and cracks can occur in the housing. Also, the sealing joints between the breather hoses can become dry and cannot seal.

The faulty oil separator or hoses cause the following symptoms: Engine idle speed fluctuation and stalling, whistling noises from the engine at idle speed, and an increase in oil consumption.

Possible fault codes stored:

P0507 Idle Control System RPM: Higher than expected.

P2177 Mixture too lean off Idle: Upper limit exceeded.

P2187 Mixture too lean at idle.

The oil separator and breather hoses are available separately or as a complete kit.

For more technical information please visit: partsfinder.bilsteingroup.com