

Important technical note relating to this unit

The ignition switch can be defective causing the starter motor to either keep running resulting in the starter motor burning out prematurely or to not turn at all.

Please double check before ordering and fitting.