















COMFORT

particle filter



FOR  
**HYUNDAI**  
**KIA**

**ELANTRA IV (06/10 >) / ELANTRA V (03/11 >) / I30 I / I30 II / CARENS IV (03/12 >)**  
**CEE'D II / SPORTY WAGON II (05/12 >)**



**715816**

FH934



PA

WANT TO  
KNOW MORE?



[www.valeo-techassist.com](http://www.valeo-techassist.com)

Valeo Service - Société par Actions Simplifiée - Capital de 12 900 000 € - 70, rue Pleyel, 93285 Saint-Denis Cedex - France - B 306 486 408 RCS Bobigny









COMFORT

particle filter



FOR  
**HYUNDAI** ELANTRA III (09/06 >)



**715816**  
FH934



WANT TO  
KNOW MORE?



[www.valeo-techassist.com](http://www.valeo-techassist.com)