



93422

0375P2, 9677062780, 1609652780, 0375S6, 0375S8, 0375S7, 9674962080, 9688361580



CITROËN, DS, PEUGEOT

11/2009 >



2.0 BLUEHDI/HDI 2.0 HYBRID/HYBRID4 100-120 KW

DWIOCTED4, DWIOFD, DWIOCB, DWIOBTED4

SUBJECT

COOLANT CONNECTION

CAN BE LEFT EMPTY IN VEHICLES WITHOUT WATER COOLING SYSTEM FOR THE TURBO



NISSENS TURBO #93422

Coolant connection flange.

Can be left empty (as not connected) by applications without water cooling for the turbo.

BACKGROUND

Depending on application, various turbocharger models are designed with a coolant circuit enclosing the bearing housing. If the vehicle, however, is not equipped with a dedicated water cooling circuit for the turbo, i.e. without dedicated ducts system from the engine cooling system to the turbo, the turbo does not require the connection. One Nissens turbo model applies for both vehicles with and without water cooling of the turbo and covers two various OE items.

RECOMMENDED SOLUTION

If the vehicle where Nissens part no. #93422 is to be fitted does not apply a dedicated water cooling for the turbo, you can install it leaving the coolant connection flange empty.



Always consult Nissens' catalogue to make sure that the turbo model fits the given vehicle/engine version. **NB!** Installing the new turbo from Nissens, always conform with the installation instruction included in the product box.



