



## LuK Service Info



# Visual features of LuK DMF

## External differences between LuK DMF and OE version


Manufacturers: Nissan, Renault

Models: Qashqai II,  
Captur II, Grand Scenic IV,  
Kadjar, Megane IV,  
Scenic IV,  
Kangoo 3

Fuel type: Diesel

Engine code: K9K-647/649/872/873/877

Art.-Nr.: 415 1078 09



For current assignment see parts catalog

Image 1: Visual comparison of LuK DMF (left) and OE DMF (right)

Being in constant contact with the market, we have found that sometimes our customers have complaints related to visual differences between OE spare parts and Schaeffler components.

The main visual features of the LuK DMF are as follows:

- the CPA system is located inside the DMF, unlike the OE version with an externally located absorber
- another shape of the primary mass outer ring

One of the striking examples is the LuK DMF Art.-Nr. 415 1078 09, which differs significantly from the OE versions (Image 1).

Despite the visual differences, the design of the LuK DMF Art.-Nr.: 415 1078 09 fully meets the technical requirements of the vehicle manufacturer and is able to completely replace the OE versions without any additional technical difficulties.

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER  
**REP>XPERT**