

Corteco Service Information No. 00048-EN
www.corteco.com www.ecatcorteco.com



Service Information:	Suspension Strut Support Mount with Ball Bearing
Corteco No.	80004545, 49470888, 49102312
Make	BMW
Model	various models of series 1, 2, 3, 4
Fitting position	Front axle both sides

SUSPENSION STRUT MOUNT WITH BALL BEARING



Art.no. 80004545
 6 x M8 hole
 for vehicles without M sports suspension



Art.no. 49470888
 6 x M8 hole
 for vehicles with M sports suspension



Art.no. 49102312
 3 x M10 hole
 for vehicles without M sports suspension

The manufacturer installs three different strut mounts in current car models. These differ in rubber hardness, number of holes (3 or 6), and size of threaded holes (M8 or M10).

CAUTION!

Before replacing the strut mount, always check which version of the strut mount is installed in your vehicle. Determining the exact part identification on the vehicle is essential.

Mixed installation of M8 and M10 strut mounts is not permitted due to a difference in stiffness.

Don't take a risk – Choose Corteco original quality.