



INA Service Info



Over-running alternator pulley 535 0263 10

Visual differences

Manufacturers: Hyundai, Kia

Models:

Hyundai: Grand Santa Fe, Santa Fe II, Santa Fe III, ix 35

Kia: Carnival III, Grand Carnival III, Sorento II, Sportage

Engines: D4HA, D4HB

Transmission: Automatic

Alternator: Denso 104210-1060

Part no.: 535 0263 10



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0263 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT