



F Notice

GB Note

D Notiz

SP Prospecto

I Nota




NL Kote uiteenjetting

P Nota

PL Informacja



valeo added



GB - Risk of corrosion. Make sure the engine splash shield is installed

F - Risque de corrosion. Assurez-vous que la protection sous-moteur est présente

D - Korrosionsgefahr. Stellen Sie sicher, dass die Unterbodenverkleidung vom Fahrzeug montiert ist

SP - Riesgo de corrosión. Asegúrese de que el protector contra salpicaduras del motor esté instalado

I - Rischio di corrosione. Assicurarsi che il paraspruzzi del motore sia installato

NL - Risico op corrosie. Zorg ervoor dat de motorbeschermplaat geïnstalleerd is.

PL - Ryzyko korozji. Upewnij się, że osłona silnika jest zainstalowana

P - Risco de corrosão. Certifique-se de que a proteção contra respingos do motor está instalada

R - Опасность коррозии. Убедитесь, что штатная защита двигателя установлена

[www.valeoservice.com](http://www.valeoservice.com)

Valeo Service  
70, rue Pleyel - 93285 Saint-Denis Cedex - France  
Tel. : +33 (0)1 49 45 32 32

**Valeo**  
Service