


Bulletin 0019

FBK 745

Important Fitment Information

Please note that some examples of this bearing are designed with a different sealing system. If the two end plates are of a different colour then the GOLD side must be fitted inboard (i.e. towards the centre of the vehicle)



Note the Gold colour is an inserted section