


Peugeot 307 01-05 Original Vehicle Before Assessment



Peugeot 307 01-05 Original Centre Grille



Peugeot 307 01-05 TONG YANG Centre Grille





TYG Centre Grille L/H



Original Centre Grille L/H

Peugeot 307 01-05



TYG Centre Grille R/H



Original Centre Grille R/H

Peugeot 307 01-05

- No Faults Identified
- Comparative Fit Quality To Original
- VTF Judgement: **PASS**