



VOLKSWAGEN TIGUAN (6/11 >)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. B 15 07 66697 026.015 entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange vorne Grundiert- mit 2 Löchern für die Sensoren und 2 Löchern für die PDC

153.29.9160


den 11/06/2015

TÜV SÜD AUTOMOTIVE GmbH


Zertifikat – Nr.: B 15 07 66697 026.015
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

Original Equipment



Tested product



Zertifikat – Nr.: B 15 07 66697 026.015
Certificate – No.

Original Equipment




Tested product



Zertifikat – Nr.: B 15 07 66697 026.015
Certificate – No.

Original Equipment	Tested product
	
	 15329.9120 23.06/2013 EuroStamp
	 9.9120 06/2013

Zertifikat – Nr.: B 15 07 66697 026.015
Certificate – No.

Original Equipment	Tested product
 A photograph of a rectangular metal component with a central circular opening. The component is mounted on a larger metal plate. The central opening has a flange with several small holes. The component is labeled 'R2' on the right side.	 A photograph of the same rectangular metal component as the original equipment, but with a different internal structure. The central opening is larger and has a different flange design. The component is labeled 'R2' on the right side.
 A photograph of the original equipment from a side angle, showing the thickness of the component and the mounting plate.	 A photograph of the tested product from a side angle, showing the thickness of the component and the mounting plate.
 A close-up photograph of the central circular opening of the original equipment, showing the flange and the mounting plate.	 A close-up photograph of the central circular opening of the tested product, showing the flange and the mounting plate.

Zertifikat – Nr.: B 15 07 66697 026.015
Certificate – No.

Original Equipment	Tested product
	
	
	