



OPEL INSIGNIA (5/09 >)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. **B 12 07 66697 015** entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange vorne grundiert mit Löchern für die PDC


101.35.9160

den 28/06/2012

TÜV SÜD AUTOMOTIVE GmbH

Zertifikat – Nr.: B 12 07 66697 015
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

| Original Equipment | Tested product |
|--|--|
|  A close-up photograph of the original equipment connector. It features a central circular opening with a textured, porous interior. The connector is mounted on a white plastic base with two vertical rows of small circular holes on either side. |  A close-up photograph of the tested product connector. It is a similar circular component with a textured interior, mounted on a white plastic base with four screws around the perimeter. |
|  A side-view photograph of the original equipment connector, showing its black plastic housing and the connection point on the left side. |  A side-view photograph of the tested product connector, showing its white plastic housing and the connection point on the left side. |
|  A front-view photograph of the original equipment connector, showing the circular opening and the surrounding metal frame. |  A front-view photograph of the tested product connector, showing the circular opening and the surrounding metal frame. |

Zertifikat – Nr.: B 12 07 66697 015
Certificate – No.

| Original Equipment | Tested product |
|---|---|
|  |  |
|  |  |
|  |  |